

- Reviewed original design drawings for 1985 construction of addition.
- Reviewed timing of ceiling removal with RebuildEx.
- Thursday Feb. 21 performed alignment survey of shoring posts, with RebuildEx.
- Identified few shoring posts either loose/set on non-structural element or not aligned vertically.
- Next step is to plot posts locations to scale and determine which ones need to be adjusted.